

30 Aug 60

List of bolts + screws,

Skin

Part A = 4 rows each of 6 screws = 48

9 pcs x 48 = 432

Part B = 2 rows of 10 screws = 20

36 pcs x 20 = 720

Total 1152

Buy 9 gross = 1296, Round head aluminium wood screws $1\frac{1}{4}$ " x #8

Part A = 1 row of 6 machine screws = 6

9 pcs x 6 = 54

Part B = 1 row of 10 machine screws = 10

36 x 10 = 360

Around edge angle, one per foot

100

Total 514

Buy 4 gross = 576, Round head aluminium machine screws 1" x #8 x 32 with nuts

Flat washers.

1 under each wood screw

1152

2 for each machine screw 2 x 514

1028

2180

Buy 2500 large flat aluminium washers with $\frac{3}{16}$ " hole.

30 Aug 60

Outside ring of rib support rods	72 rods	7
Middle " " " " "	72 "	
Inside " " " " "	<u>36 "</u>	
	180 rods	

Top of each rod has one bolt	180
Center ring has 2 bolts / rib 2×36	<u>72</u>
Total	252

Buy 300, $\frac{1}{4}$ " \times $1\frac{1}{4}$ " galvanized machine bolts & nuts

Bottom of each rod has one bolt	180
36 ribs have 2 bolts / rib at joints	<u>72</u>
Ends of legs of parapet have 4, 8×4	32
Hinges at bottom of legs 4×8	<u>32</u>
Total	316

Buy 350, $\frac{1}{4}$ " \times $2\frac{1}{2}$ " galvanized machine bolts & nuts

Buy 600, $\frac{1}{4}$ " galvanized washers for above (3 lbs)