


Zero out resistance
on Ohms Adjust

X 1 = 5.4Ω
 X 10 = 51Ω
 X 100 = 550Ω
 X 1000 = 560Ω

11.5V battery



25
 25
 25

2
 29

12x15
 5
 3.3

Trimable
 Tester
 Model 333

