


Make one of brass.



Keyway $\frac{1}{8}$ " wide milled $\frac{1}{16}$ " deep into threads.

Grote Reber
Charge 19.1-11 6-5-50