THE BUDA COMPANY · HARVEY, ILLINOIS August 6, 1951

AIR MAIL

Grace Brothers, Ltd. P. O. Box 78 Honolulu 10, Hawaii

ATTENTION: Mr. Harry E. Murray

Gentlemen:

As requested in your letter of July 16, we are pleased to enclose two (2) copies of Instruction and Maintenance Manual for Engine Model 4DT-212.

Concerning the changes necessary to govern this engine at a lower speed, it will only be necessary to change the governor spring.

The spring required to govern the engine at 1800 RPM is Part No. B-3136, priced at \$.90.

It will not be necessary to change the governor weights.

COPY

Trusting the above and enclosed meets with your satisfaction, we remain

Yours very truly, THE BUDA COMPANY /s/t/ R. J. GRENIER Export Department

RJG/jw Enc