

6 Sept 60

Inspection shows that my mirror was dismantled at Sterling, Virginia in 1952 when it was positioned with front pointing east. The observer stood at back of machine looking east. Thus the four channel frames to support top wheels are marked

observer ⊕ →	WL (west left) Back.	REAR L (unmarked REAR for EAST) (east left) Front	→ east
	WR (west right)	ER (east right)	

all the rest of wooden pieces can now be oriented to fit the above. One side circle on north side, the other on south side.